



Specialty Products **FAQ**

Part number 67410

EZ Arm for Kia Optima

Q1: The 67410 Arm that I have won't fit into the bushing pocket on the knuckle – what's wrong?

A1: After this arm was originally released, Kia apparently made a subtle machining change to their knuckle that can cause the early-style SPC arm to not fit. Early 67410 arms have the same bushing on both ends – with the inner sleeve that protrudes farther on one side than the other. To solve the fitment problem, we have changed the bushing on the 'short end' (i.e. closer to the hex adjuster and intended for use on the knuckle end in the car) to have a centered inner sleeve. This later arm will fit all listed years with no modifications required, but if you have the earlier 'double-offset bushing' version, you have two options:

1. Grind the inside of the knuckle pocket slightly to allow the offset bushing to fit. (Very little material needs to be removed to allow the arm to fit.)
2. Contact SPC to exchange for an updated arm.

