

Part number 67430



Honda CR-V Rear EZ Arm XR

Q1: The ABS wiring will not attach to the ABS bracket supplied with the 67430 arm. What do I do?

A1: The ABS wiring for some applications of the 67430 arm may not mate with the ABS bracket supplied with the 67430 arm. Reinstalling the bracket so it is captured by the other jam nut and modifying the end of the bracket will allow the ABS wiring to mount to the bracket. See the illustration below.

